



## U. S. Chemical Safety and Hazard Investigation Board

# RECOMMENDATION STATUS CHANGE SUMMARY

<b>Report:</b>	Intercontinental Terminal Company (ITC) Tank Fire
<b>Recommendation Number:</b>	2019-01-I-TX-R4
<b>Date Issued:</b>	July 6, 2023
<b>Recipient:</b>	Intercontinental Terminals Company, LLC
<b>New Status:</b>	Open – Awaiting Response or Evaluation/Approval of Response
<b>Date of Status Change:</b>	Not Applicable – Initial Status

### Recommendation Text:

*Install remotely operated emergency isolation valves configured to “Fail-Closed” for all atmospheric storage tanks that contain highly hazardous chemicals or liquids with a flammability rating of NFPA-3 or higher at the ITC Deer Park terminal.*

### Board Status Change Decision:

#### A. Rationale for Recommendation

On March 17, 2019, a loss of containment and fire occurred at the Intercontinental Terminals Company (ITC) terminal facility in Deer Park, Texas. The incident resulted from the seal failure of a pump operating in conjunction with Tank 80-8, an 80,000 barrel (3.36 million gallon) above ground atmospheric storage tank containing a mixture of naphtha and butane.

The incident did not result in any injuries. However, the fire burned for three days and spread from Tank 80-8 to the other fourteen tanks located within the same containment area. All fifteen tanks were destroyed. On March 22, 2019, the containment area wall partially collapsed releasing approximately 500,000 barrels (21 million gallon) of a mixture of petroleum products, firefighting foam, and water into Tucker Bayou and adjacent waterways including the Houston Ship Channel.

The U.S. Chemical Safety and Hazard Investigation Board (CSB) investigated the incident and found several safety issues including ineffective mechanical integrity and maintenance practices for the facility’s product transfer pumps, a lack of safety systems at the facility’s 80s tank farm, and a lack of regulatory coverage under the Occupational Safety and Health Administration’s (OSHA’s) Process Safety Management standard (PSM) and the Environmental Protection Agency’s (EPA’s) Risk Management Program rule (RMP) for the contents of tank 80-8 at the time of the incident. As a result of these findings, the CSB issued five recommendations to the Intercontinental Terminals Company, LLC. This status change summary addresses **CSB Recommendation No. 2019-01-I-TX-R4**.